

Use without coolant fluid allowed!

 $Torque\ max.\ (M1/M2) = 80 / 80\ [Nm]$ $Speed\ max.\ (n1/n2) = 4000\ /\ 4000\ [1/min]$

Gear ratio (i)=n1:n2 = 1:1 Pressure (pmax) = 70 [bar] Axial Bohr und Fräskopf Axial drilling and milling head





141647

40.75C51809IKD