

 $Speed\ max.\ (n1/n2) = 8000\ /\ 8000\ [1/min]$

Gear ratio (i)=n1:n2 = 1:1 Pressure (pmax) = 70 [bar] Radial drill. and mill. head offset

80.25VX3L5480RLIKTFR

190809

